





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD...

- 16 A 962 755 AA
- 17 A 4109 AA
- 19 B 0003 AA
- 21 A 860 807 AA
- 23 A 860 806 AA
- 27 B 0024 AA
- 28 A 860 873 AA




IDEALRAIN CUBE

A 5862 .. A 5835 ..

0513 / A 866 591
 (+ A 865 612)




Made in Germany



Ideal Standard International BVBA
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com





	P bar		MAX. 10			Q (3 bar)
	T °C					I/min
						8
						11